

# Granlunds vattenkvalitet 2020

Sammanställning över provtagningar av handpumpar och badvatten

År ==>	2015	2016	2017	2018	2019	2020
Pumpnr						
1	OK	OK	OK	OK	OK	OK?
2	OK?	OK	OK?	OK	OK?	OK?
3	OK?	OK?	-	-	-	-
4	OK	OK	OK	OK	OK	OK
5	OK	OK?	OK	OK	OK	OK
6	OK	OK	OK	OK	OK	OK
7	OK	OK?	-	OK	OK	OK
8	OK?	OK	OK	OK	OK	OK?
9	Ej OK	OK	OK?	OK?	OK	OK
10	OK?	OK?	OK	OK	OK	OK
11	OK?	EJ OK	-	OK	OK	OK
12	OK	OK	OK	OK	OK	OK
13	OK	OK?	OK	OK	OK	OK
14	OK	OK	OK?	OK?	OK	OK
15	OK	OK?	OK?	OK	OK?	OK
Lammsjön bad	OK	OK	OK	OK	OK	OK

OK = Tjänligt

OK? = Tjänligt med anmärkning

Ej OK = Otjänligt

- = Ingen provtagning möjlig