

Granlunds vattenkvalitet 2023

Sammanställning över provtagningar av handpumpar och badvatten

År ==>	2019	2020	2021	2022	2023
Pumpnr					
1	OK	OK?	OK	OK	OK?
2	OK?	OK?	OK?	OK?	OK?
3	-	-	OK	OK?	OK?
4	OK	OK	OK?	OK	OK
5	OK	OK	OK	OK	OK
6	OK	OK	OK	OK	OK
7	OK	OK	OK	-	OK
8	OK	OK?	OK?	OK	OK
9	OK	OK	OK?	Ej OK	Ej OK
10	OK	OK	OK	Ej OK	OK?
11	OK	OK	OK	OK?	OK?
12	OK	OK	OK?	OK?	OK?
13	OK	OK	OK	OK	OK
14	OK	OK	OK?	OK	Ej OK
15	OK?	OK	OK	OK?	OK?
Lammsjön bad	OK	OK	OK	OK	OK

OK = Tjänligt

OK? = Tjänligt med anmärkning

Ej OK = Otjänligt

- = Ingen provtagning möjlig